

FACILITY INSPECTION TOOL (FIT) WORKSHEET

Good Repair Standard

1. Gas Leaks	6. Pest/Vermin Infestation	11. Hazardous Materials (interior and exterior)
2. Mechanical Systems	7. Electrical (interior and exterior)	12. Structural Damage
3. Sewer	8. Restrooms	13. Roofs (observed from the ground, inside/outside)
4. Interior Surfaces (floors, ceilings, walls, window casings)	9. Sinks/Fountains (inside and outside)	14. Playground/School grounds
5. Overall Cleanliness	10. Fire Safety	15. Windows/Doors/Gates/Fences (interior and exterior)

School: Adams School

Date of inspection: September 12, 2011

Rm #		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
C	Classroom K															
12	Classroom 1 st															
9	Classroom 2 nd															
5	Classroom 3 rd															
8	Classroom 4 th															
26	Classroom 5 th															
1	Classroom 6 th															

Rating: # = good repair, D = deficiency, X = extreme deficiency, NA = not applicable

Good Repair Standard

1. Gas Leaks	6. Pest/Vermin Infestation	11. Hazardous Materials (interior and exterior)
2. Mechanical Systems	7. Electrical (interior and exterior)	12. Structural Damage
3. Sewer	8. Restrooms	13. Roofs (observed from the ground, inside/outside)
4. Interior Surfaces (floors, ceilings, walls, window casings)	9. Sinks/Fountains (inside and outside)	14. Playground/School grounds
5. Overall Cleanliness	10. Fire Safety	15. Windows/Doors/Gates/Fences (interior and exterior)

Rm #		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
K-RR	Boys Restroom															
K-RR	Girls Restroom															
4	Spanish/Math															
4-RR	Boys Restroom															
4-RR	Girls Restroom															
10-B	Speech															
		Williams Signage Missing														
10-A	Psych															
		Williams Signage Missing														
15	Library				D											
		Damaged rug - Recommend rug to be replaced														
16	Computer Lab															

Rating: # = good repair, D = deficiency, X = extreme deficiency, NA = not applicable

Good Repair Standard

1. Gas Leaks	6. Pest/Vermin Infestation	11. Hazardous Materials (interior and exterior)
2. Mechanical Systems	7. Electrical (interior and exterior)	12. Structural Damage
3. Sewer	8. Restrooms	13. Roofs (observed from the ground, inside/outside)
4. Interior Surfaces (floors, ceilings, walls, window casings)	9. Sinks/Fountains (inside and outside)	14. Playground/School grounds
5. Overall Cleanliness	10. Fire Safety	15. Windows/Doors/Gates/Fences (interior and exterior)

Rm #		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
20-RR	Boys Restroom															
20-RR	Girls Restroom															
21B	CELDT Coord Office															
29	Art Class														D	
		Roof leaks and stained ceiling tile														

Rating: # = good repair, D = deficiency, X = extreme deficiency, NA = not applicable

Good Repair Standard

1. Gas Leaks	6. Pest/Vermin Infestation	11. Hazardous Materials (interior and exterior)
2. Mechanical Systems	7. Electrical (interior and exterior)	12. Structural Damage
3. Sewer	8. Restrooms	13. Roofs (observed from the ground, inside/outside)
4. Interior Surfaces (floors, ceilings, walls, window casings)	9. Sinks/Fountains (inside and outside)	14. Playground/School grounds
5. Overall Cleanliness	10. Fire Safety	15. Windows/Doors/Gates/Fences (interior and exterior)

Rm #		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
31	Storage															
37	Science Lab															
38	Cafeteria/MPR				D											
		Missing and loose ceiling tile														
38	Kitchen															
39	Staff Lounge															
39	Staff Restroom															
39	Staff Restroom															

Rating: # = good repair, D = deficiency, X = extreme deficiency, NA = not applicable

Good Repair Standard

1. Gas Leaks	6. Pest/Vermin Infestation	11. Hazardous Materials (interior and exterior)
2. Mechanical Systems	7. Electrical (interior and exterior)	12. Structural Damage
3. Sewer	8. Restrooms	13. Roofs (observed from the ground, inside/outside)
4. Interior Surfaces (floors, ceilings, walls, window casings)	9. Sinks/Fountains (inside and outside)	14. Playground/School grounds
5. Overall Cleanliness	10. Fire Safety	15. Windows/Doors/Gates/Fences (interior and exterior)

Rm #		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
ADMINISTRATION ROOM 40																
	Principal Office															
	Office Coordinator															
		UPC Complaint forms available? Y														
Office Asst.																
Counselor Office																
Counselor Office																
Health Office																
Health Office Restroom																
Workroom																

Rating: # = good repair, D = deficiency, X = extreme deficiency, NA = not applicable

Good Repair Standard

1. Gas Leaks	6. Pest/Vermin Infestation	11. Hazardous Materials (interior and exterior)
2. Mechanical Systems	7. Electrical (interior and exterior)	12. Structural Damage
3. Sewer	8. Restrooms	13. Roofs (observed from the ground, inside/outside)
4. Interior Surfaces (floors, ceilings, walls, window casings)	9. Sinks/Fountains (inside and outside)	14. Playground/School grounds
5. Overall Cleanliness	10. Fire Safety	15. Windows/Doors/Gates/Fences (interior and exterior)

Rm #		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Play Area K																
Play Area 1-3																
Play Area 4-6																
Ball Courts																
Walkways Blacktop															D	
		Some walkways throughout site need new black top or patching														
Fields																
Fences & gates																
Parking Lot #1																
Parking Lot #2																

Rating: # = good repair, D = deficiency, X = extreme deficiency, NA = not applicable